## 2014 Consumer Confidence Report

Water System Name:

**Desmond Rd WS #3, ID #2700547** 

(aka Ed's Water Company #2)

We test the drinking water quality for many constituents as required by state and federal regulations. This report shows the results of our monitoring for the period of January 1 - December 31, 2014 and may include earlier monitoring data.

Este informe contiene información muy importante sobre su agua potable. Tradúzcalo ó hable con alguien que lo entienda bien.

Type of water source(s) in use: One Groundwater well.

Name & general location of source(s): Well #1 is located at 11 Desmond Road in Salinas, CA.

Drinking Water Source Assessment information: See attached Vulnerability Assessment.

Time and place of regularly scheduled board meetings for public participation:

Time and place of Board meetings
that are open to the public are announced to consumers.

For more information, contact: Karen Sherman

# herman Phone: (831) 663-6146 TERMS USED IN THIS REPORT

Report Date:

3/6/15

Maximum Contaminant Level (MCL): The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible. Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.

Maximum Contaminant Level Goal (MCLG): The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by the U.S. Environmental Protection Agency (USEPA).

**Public Health Goal (PHG):** The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency.

Maximum Residual Disinfectant Level (MRDL): The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

Maximum Residual Disinfectant Level Goal (MRDLG): The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

**Primary Drinking Water Standards (PDWS)**: MCLs and MRDLs for contaminants that affect health along with their monitoring and reporting requirements, and water treatment requirements.

Secondary Drinking Water Standards (SDWS): MCLs for contaminants that affect taste, odor, or appearance of the drinking water. Contaminants with SDWSs do not affect the health at the MCL levels.

**Treatment Technique (TT)**: A required process intended to reduce the level of a contaminant in drinking water.

**Regulatory Action Level (AL)**: The concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow.

**Variances and Exemptions**: State Board permission to exceed an MCL or not comply with a treatment technique under certain conditions.

**ND**: not detectable at testing limit

**ppm**: parts per million or milligrams per liter (mg/L)

**ppb**: parts per billion or micrograms per liter (μg/L)

ppt: parts per trillion or nanograms per liter (ng/L)

**ppq**: parts per quadrillion or picogram per liter (pg/L)

pCi/L: picocuries per liter (a measure of radiation)

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

#### Contaminants that may be present in source water include:

- *Microbial contaminants*, such as viruses and bacteria, that may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- *Inorganic contaminants*, such as salts and metals, that can be naturally-occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- Pesticides and herbicides, that may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.
- Organic chemical contaminants, including synthetic and volatile organic chemicals, that are by-products of industrial processes and petroleum production, and can also come from gas stations, urban stormwater runoff, agricultural application, and septic systems.
- Radioactive contaminants, that can be naturally-occurring or be the result of oil and gas production and mining activities.

In order to ensure that tap water is safe to drink, the USEPA and the State Water Resources Control Board (State Board) prescribe regulations that limit the amount of certain contaminants in water provided by public water systems. State Board regulations also establish limits for contaminants in bottled water that provide the same protection for public health.

Tables 1, 2, 3, 4, 5, 7, and 8 list all of the drinking water contaminants that were detected during the most recent sampling for the constituent. The presence of these contaminants in the water does not necessarily indicate that the water poses a health risk. The State Board allows us to monitor for certain contaminants less than once per year because the concentrations of these contaminants do not change frequently. Some of the data, though representative of the water quality, are more than one year old.

TABLE 1 –	SAMPLING	RESULT	S SHO	WING THE D	ETECTION	OF COLIF	FORM BACTERIA
Microbiological Contaminants (complete if bacteria detected)	Highest No. of Detections	No. of months in violation		М	MCL		Typical Source of Bacteria
Total Coliform Bacteria	(In a mo.) <u>4*</u>	1*		More than 1 sample in month with a detection		0	Naturally present in the environment
Fecal Coliform or E. coli	(In the year) $\underline{0}$	0		repeat sample total coliforn sample also	A routine sample and a repeat sample detect total coliform and either sample also detects fecal coliform or <i>E. coli</i>		Human and animal fecal waste
TABLE 2	- SAMPLIN	IG RESUI	LTS SHO	OWING THE	DETECTION	ON OF LEA	D AND COPPER
Lead and Copper (complete if lead or copper detected in the last sample set)	Sample Date	No. of samples collected	90 <sup>th</sup> percent level detecte	exceeding	AL	PHG	Typical Source of Contaminant
Lead (ppb)	11/26/14	5	ND	0	15	0.2	Internal corrosion of household water plumbing systems; discharges from industrial manufacturers; erosion of natural deposits
Copper (ppm)	11/26/14	5	0.026	0	1.3	0.3	Internal corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives
	TABLE 3	– SAMPL	ING RE	SULTS FOR	SODIUM A	AND HARDI	NESS
Chemical or Constituent (and reporting units)	Sample Date	Level Detecto		Range of Detections	MCL	PHG (MCLG)	Typical Source of Contaminant
Sodium (ppm)	12/11/12	27		27	none	none	Salt present in the water and is generally naturally occurring
Hardness (ppm)	12/11/12	65		65	none	none	Sum of polyvalent cations present in the water, generally magnesium and calcium, and are usually

<sup>\*</sup>Any violation of an MCL or AL is asterisked. Additional information regarding the violation is provided later in this report.

2014 SWS CCR Form Revised Jan 2015

TABLE 4 – DE	TECTION O	F CONTAM	INANTS WI	TH A	PRIM	IARY	DRINKI	NG WATER STANDARD
Chemical or Constituent (and reporting units)	Sample Date	Level Detected		Range of MCL [MRDL]			PHG (MCLC [MRDLC	
Gross Alpha (pCi/L)	8/30/13	0.706	0.70	6	1	5	(0)	Erosion of natural deposits
Chromium (µg/l)	12/11/12	19	19	19		50	(100)	Discharge from steel and pulp mills and chrome plating; erosion of natural deposits
Fluoride (mg/l)	12/11/12	0.18 0.18		}	2	.0	1	Erosion of natural deposits; water additive which promotes strong teeth; discharge from fertilizer and aluminum factories
Nitrate [as nitrate, NO3] (mg/L)	5/9/14	2.8	2.8		45 45		45	Runoff and leaching from fertilizer use; leaching from septic tanks and sewage; erosion of natural deposits
TABLE 5 – DETH	ECTION OF	CONTAMIN	ANTS WITI	H A SE	CON	DAR	<u>Y</u> DRINK	ING WATER STANDARD
Chemical or Constituent (and reporting units)	Sample Date	Level Detecte		Range of Detections		CL	PHG (MCLG	Typical Source of Contaminant
Turbidity (NTU)	12/11/12	0.45	0.45	0.45		5	N/A	Soil runoff
Total Dissolved Solids (mg/L)	12/11/12	180	180	180		000	N/A	Runoff/leaching from natural deposits
Specific Conductance (µmhos/cm)	12/11/12	260	260		1,6	500	N/A	Substances that form ions when in water; seawater influence
Chloride (mg/L)	12/11/12	34	34		5(	00	N/A	Runoff/leaching from natural deposits; seawater influence
Sulfate (mg/L)	12/11/12	2.9	2.9	2.9 500		N/A	Runoff/leaching from natural deposits; industrial wastes	
	TABLE 6	6 – DETECTI	ON OF UNR	REGUI	ATE	D CO	NTAMIN	NANTS
Chemical or Constituent (and reporting units)	Sample Date	Level Detecte		Range of Detections		Notification Level		Health Effects Language
N/A								
Disinfection By	y-products, I	Disinfectant R	Residuals and	Disinf	ection	ı By-p	oroduct P	recursors (Federal Rule)
Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections			(M	PHG CLG) RDLG]	Typical Source of Contaminant
N/A	9/25/2013		<b>%</b>					

<sup>\*</sup>Any violation of an MCL, MRDL, or TT is asterisked. Additional information regarding the violation is provided later in this report.

#### Additional General Information on Drinking Water

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that the water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the USEPA's Safe Drinking Water Hotline (1-800-426-4791).

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. USEPA/Centers for Disease Control (CDC)

2014 SWS CCR Form Revised Jan 2015

guidelines on appropriate means to lessen the risk of infection by *Cryptosporidium* and other microbial contaminants are available from the Safe Drinking Water Hotline (1-800-426-4791).

Lead-Specific Language for Community Water Systems: If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. **Desmond Road Water System #3 / aka Ed's Water Company #2** is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline or at http://www.epa.gov/safewater/lead.

# Summary Information for Violation of a MCL, MRDL, AL, TT, or Monitoring and Reporting Requirement

VIOLATION OF A MCL, MRDL, AL, TT, OR MONITORING AND REPORTING REQUIREMENT							
Violation	Explanation	Duration	Actions Taken to Correct the Violation	Health Effects Language			
In March 2014, the MCL for Total Coliform was exceeded.	An MCL exceedance of Total Coliform means that more than 1 sample was found to be Positive in a month.	March 2013	Additional samples were collected until the water system was back in compliance with the Total Coliform MCL.	Coliforms are bacteria that are naturally present in the environment and are used as an indicator that other, potentially-harmful, bacteria may be present. Coliforms were found in more samples than allowed and this was a warning of potential problems.			

### For Water Systems Providing Ground Water as a Source of Drinking Water

TABLE 7 – SAMPLING RESULTS SHOWING FECAL INDICATOR-POSITIVE GROUND WATER SOURCE SAMPLES							
Microbiological Contaminants (complete if fecal-indicator detected)  Total No. of Detections  Sample MCL [MRDL]  [MRDL]  Typical Source of Contaminant  Typical Source of Contaminant							
E. coli	(In the year) N/A	N/A	0	(0)	Human and animal fecal waste		
Enterococci	(In the year) N/A	N/A	TT	n/a	Human and animal fecal waste		
Coliphage	(In the year) N/A	N/A	TT	n/a	Human and animal fecal waste		

## Summary Information for Fecal Indicator-Positive Ground Water Source Samples, Uncorrected Significant Deficiencies, or Ground Water TT

SPECIAL NOTICE OF FECAL INDICATOR-POSITIVE GROUND WATER SOURCE SAMPLE								
NONE.								
	SPECIAL NOTICE FOR UNCORRECTED SIGNIFICANT DEFICIENCIES							
NONE.	NONE.							
VIOLATION OF GROUND WATER TT								
TT Violation	Explanation	Duration	Actions Taken to Correct the Violation	Health Effects Language				
NONE.								

## **Summary Information for Operating Under a Variance or Exemption**

N/A.

			,				
Vulnerab	oility Summary						
System Name	Monterey County DESMOND RD WS #03 WELL 01	District No. 57 Source No.	System No.	2700547 2700547-001			
Completed by	Monterey County		<b>Date</b> May, 2001				
According to CDPH records, this Source is Groundwater. This Assessment was done using the Default Groundwater System Method.							
A source water assessment was conducted for the <u>WELL 01</u> of the <u>DESMOND RD WS #03</u> water system in <u>May, 2001</u>							
The source is considered most vulnerable to the following activities not associated with any detected contaminants:							
	Septic systems - high density	[>1/acre]					

### **Discussion of Vulnerability**

A horse corral is upgrade and borders the well lot for this water system. Manure was observed in the corral and in the well lot.

The manure has the potential to get into the source if the corral is not properly and routinely maintained.

A copy of the complete assessment may be viewed at:

Monterey County Health Department 1270 Natividad Road Room 109 California, CA 93906

You may request a summary of the assessment be sent to you by contacting:

Sandy Ayala Environmental Health Specialist (831)755-8924 (831)755-8929 (fax) ayalasa@co.monterey.ca.us